

Message Text

LIMITED OFFICIAL USE

PAGE 01 LAGOS 02161 231518Z

43

ACTION FBO-05

INFO OCT-01 AF-06 ISO-00 A-01 SSO-00 /013 W

----- 089589

O 231450Z FEB 76

FM AMEMBASSY LAGOS

TO SECSTATE WASHDC IMMEDIATE 3471

LIMITED OFFICIAL USE LAGOS 2161

FOR A/FBO AND AF/EX

E.O. 11652: N/A

TAGS: ABLD, AFSP, ASEC

SUBJECT: BUILDING REPAIRS

1. INITIAL ASSESSMENT OF DAMAGE RESULTING FROM ATTACK ON EMBASSY OB ESTIMATED AT \$8,750.
2. ABOVE ESTIMATE BASED ON LABOR AND MATERIAL REQUIRED TO REPLACE ONLY BROKEN WINDOWS WITH CONVENTIONAL GLASS AVAILABLE LOCALLY.
3. EMBASSY WOULD APPRECIATE DEPARTMENTAL COMMEN/GUIDANCE REGARDING FEASIBILITY REPLACING GLASS ALL EXISTING WINDOWS USING "LEXAN."
4. SECOND ALTERNATIVE WOULD BE TO REDUCE PRESENT WINDOW AREA BY APPROXIMATELY TWO-THIRDS USING CONCRETE BLOCK AND PLASTER TO MATCH EXISTING STRUCTURE AND REPLACE REMAINING GLASS WITH "LEXAN." THIS IS LESS ATTRACTIVE SINCE REDUCED WINDOW AREA WOULD PRECLUDE WORKING DURING FREQUENT ELECTRICAL OUTAGES ISNCE CHANCERY NOT EQUIPPED WITH SUFFICIENT AUXILIARY POWER.
5. IF PROPOSALS ITEM 3 OR 4 ABOVE CONSIDERED FEASIBLE POST WILL PROVIDE NUMBER AND PRECISE MEASUREMENTS LEXAN REQUIRED AND WASHINGTON GE-LEXAN REPRESENTATIVE, ROLAND FRIDDEL, 777 FOURTEENTH STREET N.W., CAN PROVIDE ESTIMATE COST.

LIMITED OFFICIAL USE

LIMITED OFFICIAL USE

PAGE 02 LAGOS 02161 231518Z

6. ASSUMING FUNDS AVAILABLE TO COVER ADDED COST PURCHASE

AND AIRSHIPMENT LEXAN POST WOULD PREFER PROCEED PROPOSAL
ITEM 3.

7. WHICHEVER PROCEDURE FOLLOWED, POST WILL REQUIRE ADDITIONAL
FUNDING. ADVISE SOONEST.
EASUM

LIMITED OFFICIAL USE

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 JAN 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 23 FEB 1976
Decaption Date: 01 JAN 1960
Decaption Note:
Disposition Action: RELEASED
Disposition Approved on Date:
Disposition Authority: morefirh
Disposition Case Number: n/a
Disposition Comment: 25 YEAR REVIEW
Disposition Date: 28 MAY 2004
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1976LAGOS02161
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Film Number: D760067-0201
From: LAGOS
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1976/newtext/t19760224/aaaaauln.tel
Line Count: 67
Locator: TEXT ON-LINE, ON MICROFILM
Office: ACTION FBO
Original Classification: LIMITED OFFICIAL USE
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: LIMITED OFFICIAL USE
Previous Handling Restrictions: n/a
Reference: n/a
Review Action: RELEASED, APPROVED
Review Authority: morefirh
Review Comment: n/a
Review Content Flags:
Review Date: 06 JUL 2004
Review Event:
Review Exemptions: n/a
Review History: RELEASED <06 JUL 2004 by ellisoob>; APPROVED <06 JUL 2004 by morefirh>
Review Markings:

Margaret P. Grafeld
Declassified/Released
US Department of State
EO Systematic Review
04 MAY 2006

Review Media Identifier:
Review Referrals: n/a
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
Secure: OPEN
Status: NATIVE
Subject: BUILDING REPAIRS
TAGS: ABLD, AFSP, ASEC
To: STATE
Type: TE
Markings: Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 04 MAY 2006